


Vibration case study



CASE STUDY

Vibration Increase in a Liquid Ring Compressor

By Charles Scott
TNT Reliability Services, Inc.


A significant increase in overall vibration levels was noted during routine monthly vibration monitoring of a liquid ring compressor. The machine design includes an electric motor with a nameplate rated speed of 1,200 rpm @ 400 hp, driving a liquid ring compressor with a capacity of 1,350 acfm (795 cfm) and a differential pressure of 540 kPa (78 ps). This type of machine is found primarily in petroleum refineries and chemical plants. These rugged compressors (Figure 1) handle highly toxic, explosive, and corrosive gases in applications such as flare gas, chlorine, and vinyl chloride monomer (VCM) recovery.

Figure 1. Liquid Ring Compressor



The liquid ring compressor compresses gas by rotating a vane impeller within an eccentric to a cylindrical casing. Liquid, usually water or oil, is fed into the pump and, by centrifugal acceleration, forms a moving cylindrical ring against the inside of the casing. This liquid ring creates a series of seals in the spaces between the impeller vanes, thereby forming compression chambers. The eccentricity between the impeller's axis of rotation and the casing geometric axis results in a variation of the volume enclosed by the vanes and the ring. Gas is drawn into the pump by an inlet port located at the end of the casing. The gas is trapped in the compression chambers formed by the impeller vanes and the liquid ring. The reduction in volume caused by the impeller rotation compresses the gas, which then goes to the discharge port (Figure 2).


Figure 2. Gas Compression of a Liquid Ring Compressor



SEPTEMBER 2013


Figure 3 shows the trend of overall vibration level. The vibration levels measured during the latest data collection increased dramatically compared with the previous three data collections.

Figure 3. Spectral Overall Machine Trend Data



Spectral analysis (Figure 4) of the latest data measurements indicated a dominant peak at 23,880 rpm. The frequency spectrum also contained responses, albeit to a reduced amplitude, at the second, third, and fourth harmonic of the dominant frequency. Subbands at 1,194 rpm (1 x running speed) were also evident in the spectrum. An investigation of physical machine parts in the warehouse determined that the impeller had 20 vanes. The dominant frequency of 23,880 rpm works out to the BPF (blade or vane pass frequency).

Figure 4. Vibration Spectrum Indicating BPF & BPF Harmonics



The calculation to determine BPF is as follows:

$$BPF = \text{number of blades (or vanes)} \times \text{rotational speed}$$

$$BPF = 20 \times 1,194 \text{ rpm} = 23,880 \text{ rpm}$$

Vibration response at blade or vane pass frequency is inherent in pumps, fans, and compressors and normally does not present a problem. However, large-amplitude BPF (and BPF harmonics) can be generated in a pump if the gap between the rotating vanes and the stationary diffusers is not kept even all the way around. Also, BPF (or harmonics) sometimes coincides with the system's natural frequencies, causing high levels of vibration.

High BPF can be generated if the wear ring surfaces on the shaft or if worn, loading diffusers fail. Also, high BPF can be caused by abrupt bends in the work (or duct) that create obstructions and disturb the flow path.

Figure 5 is a spectral waterfall plot that distinctly indicates increasing activity at BPF and BPF harmonics. Figure 6 compares the time waveforms of vibration during the last four data collection periods. The time waveform shows an increase in energy from 2 g peak to peak to 8 g peak to peak. The unit was taken out of service and a mechanical inspection was performed.

Figure 5. Spectrum Waterfall Indicating an Increase in BPF and BPF Harmonics






Figure 6. Time Waveform Showing Energy Increase




During machine tear-down and visual inspection, the compressor housing, bearings, and shaft were within tolerance and did not show any visible damage. However, an inspection of the impeller did indicate damage to it. The inside of the impeller (Figure 7) had visual rub marks where it had made contact with the case at some time. The markings varied in depth and correlated with the damage to the case.

Figure 7. Visual Rub Marks Noted Inside Impeller



Further investigation revealed a crack in one of the impeller vanes (Figure 8). The rubbed and cracked impeller was determined to be the probable root cause of the dramatic increase in vibration.

Figure 8. Crack Noted in Impeller Vane



This case study shows the importance of and justification for an effective vibration program at a manufacturing facility. Condition monitoring programs demonstrably contribute to the bottom line of the company.

BIOGRAPHY

Charles Scott owns TNT Reliability Services, Inc., a technical service company providing state of the art technologies to manufacturing and industrial facilities. He has over 12 years of technical equipment experience, for the past 8 specializing in vibration analysis. He holds an AAS in Industrial Technology from South Arkansas Community College and holds Vibration Institute certification as a Vibration Analyst Category II, as well as Category III Vibration Analyst certification from Motus. Scott is also certified by SDI as a Level I Airborne Ultrasound Inspector and by Reliability Testing Services as a Level I Thermographer. He can be reached at cscott@tntreliability.com.

Certification Surveillance

In order to protect the Institute members who have justly earned certification as a Vibration Analyst, the Vibration Institute wants to pursue individuals who falsify Institute certification in any manner.

If you are aware of any instance in which you believe an individual is falsifying higher certification status, please call or contact the Vibration Institute immediately.

If you are aware of any individual who you believe is violating basic ethics, please correct the individual as soon as possible. Failure to do so degrades the reputation of your certification and the Vibration Institute.

(630) 654-2254
information@vi-institute.org






Case Study

Liquid Ring
Compressor

Capacity of 795 cfm &
Differential Pressure
of 78 psi

1200 rpm




Case Study

Increase In Vane Pass Frequency & Harmonics


Energy in Time-Based Waveform Increasing

Overall Vibration Amplitude Still Considered Low at 0.12ips



Case Study

Inspection Found The
Cause - Cracked
Impeller Vane



Case Study Results

Maintenance history of the liquid ring compressors: previously, an impeller vane had broken completely off, wedging it inside the fluid end of the machine and causing a catastrophic failure. The damage caused by the component failure resulted in a total loss of the machine. The replacement cost for this machine was \$360,000, with a six-month lead time.

By finding the problem predictively, rebuilding the compressor was only \$60,000. Proactive planning due to predictive knowledge resulted in a savings of approximately \$300,000.